cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



		-							
Intersection ID: 22135	Main Str	Main Street: RIDGEBROOK_DR			WATERCREST_RD	Location:	NW		
ADA ID: E9366A98E84B	Ramp Ty	Ramp Type: PerpDiag			nitial Pass/Fail: Fail Overall Compliance: No				12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	~	Possible Solutions:		Compliance Description			Data Compliance Description		Data
		Remove & Replace Curb Ramp V	Nith	N/A	Ramp Length (in)	82.0	Yes	Ramp Slope (%)	6.3
	N S ST A	Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.1
	A A PARA	Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	C. POST			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	A Andrew			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
A CARLER HERE				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
E.		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
and the second				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	6. C			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
5				N/A	Shared Landing?	N/A			
and the second second	A latera	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
A A A A A A A A A A A A A A A A A A A	1 19 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
AN A	A. MARIN	Not i build, 1004.5.5		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	RIDGEBROOK DR	2			X Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	8.2
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	7.3		X Walk 2 X Slope (%)	0.2
Street 2 Name	WATERCREST RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None			10/4	Road Slope (%)	4.3	N/A	Clear Space?	N/A
	None				Road X Slope (%)	4.0 6.9	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	0.9 N/A	N/A	Storm Grate/Utility Hazard?	N/A N/A
		Total Cost: \$3	3200.00	11/2	Obstruction Type	17/4		Storm Grate/Utility Type	11/2
		10tai 00st. 🌵 J	200.00		Observation Type	N/A		otomi Grate/Otimity Type	N/A
						IN/A	1		IN/A

Yes Surface Condition? (G/P)

Good

