## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 3955	tersection ID: 3955 Main Street: APPLEVALLEY_CT Cross Street: ARMITAGE_DR								w
ADA ID: E939D835309A		Ramp Type: BlendTrans1			ail: Fail Overall O	Location: o Severity Score:	42.5		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component					-1210
Possible Solutions:								liance Description	Data
				_		58.0	Yes		3.5
		Remove & Replace Curb Ram Two New Directional Ramps o		N/A	Ramp Length (in)			BlendTrans Slope (%)	
		Equivalent.	ſ	No	Ramp Width (in)		No	BlendTrans XSlope (%)	8.9
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)		N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	G	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the second se	A CARLES	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
TUILLE			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
Caller and the second se				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Not Found, R304.5.1, R304.5.3			3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			-	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name	APPLE VALLEY CT	-			X Walk 1 Slope (%)	6.3		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	4.0		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	4.0		Clear Space?	N/A
	N/A				Road X Slope (%)	4.0 6.3	N/A	Clear Space to XWalk (in)	N/A
				N/A	,	6.3 N/A	N/A	1 ()	N/A N/A
		Tatal Quark		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

18.0