


Access Compliance Report

Public Rights-of-Way (Curb Ramps)

Intersection ID: 54301	Main Street: GOLF_LINKS_DR	Cross Street: PROVIDENCE_FARM_LN	Location: NE
ADA ID: E9621822D01F	Ramp Type: Directional1	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 0	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	86.0	No	Grade Break?	No
			Yes	Ramp Width (in)	74.0	N/A	Grade Break Slope (%)	3.8
			Yes	Ramp Slope (%)	5.7	N/A	Grade Break XSlope (%)	2.4
			Yes	Ramp XSlope (%)	1.9			
			Yes	Flare Type LT	N/A	Yes	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
			Yes	Landing Length (in)	100.0	Yes	DWS Provided?	Yes
			Yes	Landing Width (in)	74.0	Yes	DWS Contrast?	Yes
Surveyor Notes:		Yes	Landing Slope (%)	1.1	Yes	DWS Length (in)	24.0	
N/A		Yes	Landing X Slope (%)	1.2	Yes	DWS Full Width?	Yes	
		N/A	Landing Curb? (Y/N)	N/A	Yes	DWS Offset LT (in)	44.0	
		N/A	Shared Landing?	Yes	Yes	DWS Offset RT (in)	2.0	
		Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	0.9	
		Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.6	
		N/A	Painted X Walk1?	No		Road Slope (%)	2.0	
			X Walk 1 Direction	To SW		Road X Slope (%)	0.7	
			X Walk 1 Width (in)	N/A		Clear Space?	Yes	
			X Walk 1 Slope (%)	2.0	N/A	Clear Space to XWalk (in)	N/A	
			X Walk 1 X Slope (%)	0.7	Yes	Storm Grate/Utility Hazard?	No	
		N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
		Yes	Any Obstructions?	No			N/A	
			Obstruction Type		Yes	Surface Condition? (G/P)	Good	
					N/A	Curb Slope (%)	5.7	
PROW/ADA:								
R304.5.2								

