## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Good

Intersection ID: 19996	tersection ID: 19996 Main Street: ARCHDALE_DR		Cross Street: ROSECREST_DR				Location:	SE	
ADA ID: E9BD1C14B69A Ramp Type: PerpDiag		Initial I	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	33.75	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	V	Possible Solutions:		Comp	liance Description	Data	Comp	liance Description	Data
The		Remove & Replace Curb Ramp \	With	N/A	Ramp Length (in)	72.0	Yes	Ramp Slope (%)	5.8
		Two New Directional Ramps or		No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	7.8
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
ARCHDALE DR				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	A A A A A A A A A A A A A A A A A A A	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the second se	Party and	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
2			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A				
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Not		Not Found, R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	,,,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
					X Walk 1 Direction	To W		X Walk 2 Direction	To N
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name ROS	SECREST DR	_			X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	5.3
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	6.6		X Walk 2 X Slope (%)	4.2
Street 2 Name AF	RCHDALE DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	5.8	N/A	Clear Space?	N/A
					Road X Slope (%)	1.3	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

