

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15129	Main Str	Main Street: ALBEMARLE RD			Cross Street: GRAFTON PL				SE
ADA ID: E9EA420C8BAC	Ramp T	Ramp Type: Para			Initial Pass/Fail: Fail Overall Compliance: No				13.75
Codes/Mitigation Info/Possible Solution				Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 13.75 Field Measurements/Component Compliance					
	Possible Solutions:			Compliance Description Data Complia				liance Description	Data
	and the	Remove & Replace Entire Ram	D.	N/A	Ramp Length LT (in)	63.0	N/A	Ramp Length RT (in)	60.0
A AN A A A A A A A A A A A A A A A A A	-		•	Yes	Ramp Width LT (in)	60.0	Yes	Ramp Width RT (in)	60.0
Star Mall and a start of the start				Yes	Ramp Slope LT (%)	4.8	No	Ramp Slope RT (%)	9.2
MISENARUE ED				No	Ramp XSlope LT (%)	2.8	No	Ramp XSlope RT (%)	2.3
MUSERALI				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
and the second s	A STATE STATE			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	CONSIGNATION OF	Surveyor Notes:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		LT RP < 5%		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	and the the			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	* 1			N/A	Shared Landing?	N/A			
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	1 - Alter Sale	PROW/ADA:		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
A State State State		R304.5.3, R304.3.2		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	and the second second				X Walk 1 Direction	To W		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Star and a					X Walk 1 Slope (%)	5.5		X Walk 2 Slope (%)	N/A
Street 1 Name	GRAFTON PL	-			X Walk 1 X Slope (%)	1.8		X Walk 2 X Slope (%)	N/A
Stop Condition-Street 1	StopSign			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Street 2 Name	. c N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
Stop Condition-Street 2	N/A				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
					Obstruction Type			Storm Grate/Utility Type	
		Total Cost: \$	1600.00			N/A			N/A
							Yes	Surface Condition? (G/P)	Good





N/A

Curb Slope (%)

23.1