cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 16835	lain Street: HARTNESS_AV	Cross Street	: WALKER_RD			Location:	SW	
ADA ID: EA3E075EE6B5 R	Ramp Type: PerpDiag		nitial Pass/Fail: Fail Overall Compliance			o Severity Score:	21.25	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
Entrance of the second se	Possible Solutions:	Com	Compliance Description Data			Compliance Description Data		
	Remove & Replace Curb Ramp W	ith N/A	Ramp Length (in)	29.0	No	Ramp Slope (%)	9.2	
	Two New Directional Ramps or	No	Ramp Width (in)	45.0	Yes	Ramp XSlope (%)	0.2	
	Equivalent.	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	A	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	The state of the s	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
		N/A	Shared Landing?	N/A				
	PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Not Found, R304.5.1, R304.2.2	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
			X Walk 1 Direction	To E		X Walk 2 Direction	To NW	
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name WALK	ER RD		X Walk 1 Slope (%)	0.1		X Walk 2 Slope (%)	1.8	
Stop Condition-Street 2	None		X Walk 1 X Slope (%)	3.6		X Walk 2 X Slope (%)	0.7	
Street 2 Name HARTNE	ESS AV	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1 Sto	opSign		Road Slope (%)	1.1	N/A	Clear Space?	N/A	
			Road X Slope (%)	2.5	N/A	Clear Space to XWalk (in)	N/A	
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$ 32	200.00	Obstruction Type			Storm Grate/Utility Type		
				N/A			N/A	

Yes Surface Condition? (G/P)

Good

