cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 24744	Main Street: CHOATE_CR			treet:	FRESHWELL_RD	Location:	NE		
ADA ID: EA67A8C96311	Ramp Ty	Ramp Type: PerpDiag			nitial Pass/Fail: Fail Overall Compliance: No				12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		Data
THE REAL PROPERTY OF THE PROPERTY OF THE REAL PROPE		Remove & Replace Curb Ramp W	ith	N/A	Ramp Length (in)	50.0	No	Ramp Slope (%)	11.6
		Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.2
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
E A				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
H Bar		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	1 Allona	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
OTOTIE OF	Adda for			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
mile to the second	-			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
A PAN TRA BRANCE				N/A	Shared Landing?	N/A			
A STATE SAME	March A	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	A State of the state of the	R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
CARL AL				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
A Company of the second		5			X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
which has a solution				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name F	RESHWELL RD	-			X Walk 1 Slope (%)	0.4		X Walk 2 Slope (%)	2.8
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	1.4		X Walk 2 X Slope (%)	0.5
Street 2 Name	CHOATE CR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	3.2	N/A	Clear Space?	N/A
					Road X Slope (%)	2.9	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	00.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

