

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 2795 Main St	section ID: 2795 Main Street: GLEN_ROYAL_DR			HIGHLAND_CREEK_F	Location:	S		
ADA ID: EA7B0ED3EB76 Ramp Type: PerpDiag		Initial Pa	Initial Pass/Fail: Fail Overall Compliance: N				Severity Score:	12.5
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:	9	Compliance Description			Data Compliance Description		
	Remove & Replace Curb Ramp Wit Two New Directional Ramps or Equivalent.	/ith ¹	N/A	Ramp Length (in)	76.0	No	Ramp Slope (%)	9.4
			Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.6
		١	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		1	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		1	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		1	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:	1	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	1	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		I	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		1	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
<u>.</u>		I	N/A	Shared Landing?	N/A			
	PROW/ADA:	I	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	R304.2.2	1	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		I	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
		I	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name HGHLAND CREEK PY	-			X Walk 1 Slope (%)	2.7		X Walk 2 Slope (%)	0.8
Stop Condition-Street 2 None				X Walk 1 X Slope (%)	1.6		X Walk 2 X Slope (%)	0.2
Street 2 Name GLEN ROYAL DR		I	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 StopSign				Road Slope (%)	2.1	N/A	Clear Space?	N/A
				Road X Slope (%)	1.7	N/A	Clear Space to XWalk (in)	N/A
		1	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

