

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15382 Main Stu	Cross S	street:	ORANGE_ST	Location:	NW			
	Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Compliance: No			Severity Score:	13.75	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		<u>-</u>				liance Description	Data
	Remove & Replace Curb Ramp W Two New Directional Ramps or Equivalent.	Vith	N/A	Ramp Length (in)	46.0	No	Ramp Slope (%)	11.3
			Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	4.8
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	R		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A			
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
and a training of the second s				X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name FANNIE CR	-			X Walk 1 Slope (%)	1.7		X Walk 2 Slope (%)	4.4
Stop Condition-Street 2 StopSign				X Walk 1 X Slope (%)	2.2		X Walk 2 X Slope (%)	3.4
Street 2 Name ORANGE ST			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 None				Road Slope (%)	4.5	N/A	Clear Space?	N/A
				Road X Slope (%)	2.0	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
				••	N/A			N/A

Yes Surface Condition? (G/P)

Good

