cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Surface Condition? (G/P)

Curb Slope (%)

Good

9.3

Yes

No

Intersection ID: 14127	Main Stre	Main Street: BASCOM_ST			Street:	BAY_ST	Location:	S		
ADA ID: EB8985AAB894		Ramp Type: BlendTrans2			Initial Pass/Fail: Fail Overall Compliance: No					
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
Possible Solutions:				Compliance Description Data Compliance Description Data						
	1 2	14						Yes		
		Remove & Replace Curl	nal Ramps or		N/A	Ramp Length (in)	60.0		BlendTrans Slope (%)	4.1
		Equivalent.		ſ	No	Ramp Width (in)	44.0	No	BlendTrans XSlope (%)	7.4
		Equivalent.			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
					N/A	Flare Slope LT (%)		N/A	Flare Slope RT (%)	N/A
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
184		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
ALL AL		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	10				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
The second se					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	List N				N/A	Shared Landing?	N/A			
	The ALC	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R	304.5.3	5	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	The second second	, , ,			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
5 1 1 1 1 1 1 1 1 1 1 1	12 1 S. J. S. L.					X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
1 A Contraction of the	and the second					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	BASCOM ST					X Walk 1 Slope (%)	9.7		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	None					X Walk 1 X Slope (%)	0.1		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A					Road Slope (%)	0.1		Clear Space?	N/A
						Road X Slope (%)	9.7	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
			Ŧ				N/A			N/A
							IN/A			IN/A





