

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

1.3

10.8

N/A

No

N/A

8.1

0.7

N/A

N/A

N/A

N/A

N/A

9.4

Good

Storm Grate/Utility Type

Surface Condition? (G/P)

Curb Slope (%)

To NE

Intersection ID: 22794 Main Street: KALANCHOE DR **Cross Street: LIRIOPE CT** Location: W **Overall Compliance: No Severity Score:** 25 ADA ID: EC870F68A600 Ramp Type: BlendTrans1 Initial Pass/Fail: Fail

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

No



Street 1 Name Stop Condition-Street 1 Street 2 Name Stop Condition-Street 2 **KALANCHOE DR** None LIRIOPE CT StopSign Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

N/A

PROW/ADA:

Not Found, R304.5.3

Total Cost:

Compliance Description Data Compliance Description Yes N/A Ramp Length (in) 52.0 BlendTrans Slope (%) 48.0 No Yes Ramp Width (in) BlendTrans XSlope (%) N/A N/A Flare Type LT N/A Flare Type RT N/A Flare Slope LT (%) N/A N/A Flare Slope RT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A Landing Length (in) N/A N/A **DWS Provided?** N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A Landing Slope (%) DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A Painted X Walk1? No N/A Painted X Walk2? X Walk 1 Direction To SE X Walk 2 Direction N/A X Walk 1 Width (in) X Walk 2 Width (in) X Walk 1 Slope (%) 4.6 X Walk 2 Slope (%) X Walk 1 X Slope (%) 9.6 X Walk 2 X Slope (%) N/A N/A Ramp inside XWalk2? N/A Ramp inside XWalk1? Road Slope (%) 7.6 Clear Space? Road X Slope (%) 9.0 N/A Clear Space to XWalk (in) N/A N/A N/A Any Obstructions? Storm Grate/Utility Hazard?







3200.00

Obstruction Type