

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

58.0

59.5

7.0

1.5

3.8

10.4

N/A

Main Street: MAGNOLIA AV Cross Street: PARK RD Intersection ID: 15074 Location: SE Initial Pass/Fail: Fail **Overall Compliance: No** ADA ID: EC8FC6EE4A30 Ramp Type: Combination1 **Severity Score:** 37.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

Yes

Yes

Yes

No

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

Flare Traversable RT?

Ramp XSlope RT (%)

Data

20.5

68.0

11.6

0.6

73.0

48.0

N/A

No

To W

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Gutter Ponding?

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)



Street 1 Name StopSign PARK RD Stop Condition-Street 1 Street 2 Name N/A Stop Condition-Street 2 N/A Possible Solutions: Compliance Description N/A Remove & Replace Entire Ramp. Yes No Yes N/A Yes Surveyor Notes: N/A N/A N/A N/A N/A N/A PROW/ADA: N/A R304.5.3, R304.3.2 N/A N/A N/A N/A N/A N/A



Total Cost:



		X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	2.8		X Walk 2 Slope (%)	N/A
		X Walk 1 X Slope (%)	0.6		X Walk 2 X Slope (%)	N/A
1800.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	N/A		Clear Space?	N/A
		Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
	15			N/A	Any Obstruction?	N/A
					Obstruction Type	
						N/A
				N/A	Storm Grate/Utility Hazard?	N/A
35					Storm Grate/Utility Type	14,71
						N/A
		40000		Yes	Surface Condition? (G/P)	Good
	3/4	10 mg 19		l	Curb Slope (%)	2.6
	1					