cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



		-	-	-					
Intersection ID: 18794	4 Main Street: RANDOLPH_RD			Street:	REMBRANDT_CR	Location:	NW		
ADA ID: ECD10A791138	CD10A791138 Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
R. S. Car	A C C C C C C C C C C C C C C C C C C C	Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	66.0	No	Ramp Slope (%)	11.1
		Two New Directional Ramps or		Yes	Ramp Width (in)	55.0	No	Ramp XSlope (%)	3.4
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
State Rest				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
The second second				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
the second se		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
NUDI CAS		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
RELEBRIN				N/A	Shared Landing?	N/A			
the second second				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	1 2	Not Found, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
and the second s				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
- the first of the second seco	and the second			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	REMBRANDT CR	-			X Walk 1 Slope (%)	0.2		X Walk 2 Slope (%)	4.6
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	4.4		X Walk 2 X Slope (%)	0.6
Street 2 Name	RANDOLPH RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	0.5	N/A	Clear Space?	N/A
					Road X Slope (%)	3.6	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
1						N/A			N/A

Yes Surface Condition? (G/P)

Good

