

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

N/A

N/A

N/A

N/A

6.4

4.6

N/A

Intersection ID: N/A Main Street: AMAY JAMES AV **Cross Street: LESTER ST** Location: NW Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** ADA ID: ECE3252433C9 Ramp Type: Combination2 37.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance Data

54.0

50.0

13.2

5.5

27.0

48.0

N/A

No

To E

N/A

6.9

N/A

N/A

N/A

N/A

Yes

Yes

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

Flare Traversable RT?

Ramp XSlope RT (%)



Street 1 Name None Stop Condition-Street 1 **AMAY JAMES AV** Street 2 Name N/A Stop Condition-Street 2 N/A Possible Solutions: Compliance Description Remove & Replace Entire Ramp. Surveyor Notes: N/A PROW/ADA: R304.3.2, R304.5.3

Total Cost:

N/A Ramp Length LT (in) Yes Ramp Width LT (in) No Ramp Slope LT (%) Ramp XSlope LT (%) No N/A Ramp Length (in) Ramp Width (in) Yes N/A Flare Type LT N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A Landing Length (in) Landing Width (in) N/A N/A Landing Slope (%) N/A Landing X Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? N/A **Gutter Ponding?** N/A Gutter Lip Ht (in) Painted X Walk1? N/A X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slone (%)



| | | X Walk 1 X Slope (%) | 7.0 | | X Walk 2 X Slope (%) | N/A |
|---------|-----|----------------------|-----|-----|-----------------------------|------|
| 1600.00 | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| | | Road Slope (%) | N/A | | Clear Space? | N/A |
| | | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| | | | | N/A | Any Obstruction? | N/A |
| | | | | | Obstruction Type | |
| | | | | | | N/A |
| | | | | N/A | Storm Grate/Utility Hazard? | N/A |
| | | | | | Storm Grate/Utility Type | |
| | | | | | | N/A |
| *** | | | | Yes | Surface Condition? (G/P) | Good |
| | | | | | Curb Slope (%) | 1.7 |



