


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 25907	Main Street: CHALLIS_HILL_LN	Cross Street: OLD_WELL_HOUSE_RD	Location:	N
ADA ID: ED0DF8DE6CAC	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		Yes	Ramp Length (in)	97.0
			N/A	Ramp Width (in)	48.0
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Flare Type RT	N/A
			N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable RT?	N/A
			N/A	DWS Provided?	N/A
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>R304.5.3</p>			N/A	DWS Contrast?	N/A
			N/A	DWS Length (in)	N/A
			N/A	DWS Full Width?	N/A
			N/A	DWS Offset (in)	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	No
			N/A	X Walk 1 Direction	To W
			N/A	X Walk 1 Width (in)	N/A
			N/A	X Walk 1 Slope (%)	2.2
<p>Total Cost:</p> <p>\$ 3200.00</p>			N/A	X Walk 1 X Slope (%)	6.8
			N/A	Ramp inside XWalk1?	N/A
			N/A	Ramp inside XWalk2?	N/A
			N/A	Road Slope (%)	4.3
			N/A	Road X Slope (%)	2.7
			N/A	Any Obstructions?	N/A
			N/A	Obstruction Type	
			N/A	Clear Space?	N/A
			N/A	Clear Space to XWalk (in)	N/A
			N/A	Storm Grate/Utility Hazard?	N/A
			N/A	Storm Grate/Utility Type	
			N/A	Surface Condition? (G/P)	Good

