

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 27200Main Street: ANNALEXA\_LNCross Street: BALLANTYNE\_COMMONS\_PYLocation:NEADA ID: ED3A2901B6E3Ramp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 27.5

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name BALLANTYNE COMMONS PY
Stop Condition-Street 2 None
Street 2 Name N/A
Stop Condition-Street 1 N/A

/Possible Solution		Field Measurements/Component Compliance				
Possible Solutions:	Comp	iance Description	Data	Complia	nce Description	Data
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)	95.0	No	Ramp Slope (%)	9.1
	Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.2
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	N/A	Shared Landing?	N/A			
PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Not Found, R304.2.2, R302.7	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
		X Walk 1 Direction	To S		X Walk 2 Direction	N/A
	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	4.3		X Walk 2 Slope (%)	N/A
		X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	N/A
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	N/A	N/A	Clear Space?	N/A
		Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
Total Cost: \$ 185	0.00	Obstruction Type			Storm Grate/Utility Type	
			N/A			N/A
				No	Surface Condition? (G/P)	Poor





