

Access Compliance Report Public Rights-of-Way (Curb Ramps)



					_		
Intersection ID: 6041 Main St	Main Street: E_MCCULLOUGH_DR		Cross Street: KEN_HOFFMAN_DR			Location:	Ν
ADA ID: ED3BC93FE995 Ramp T	Ramp Type: Perp		Initial Pass/Fail: Fail Overall Compliance:			o Severity Score:	25
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance					
	Possible Solutions:	Compliance Description Data			Compliance Description Data		
A Start Mar Market K	Remove & Replace Entire Ramp	N/A	Ramp Length	n (in) 168.0	No	Ramp Slope (%)	13.3
B A		Yes	Ramp Width	(in) 63.0	Yes	Ramp XSlope (%)	0.6
		N/A	Flare Type L	T N/A	N/A	Flare Type RT	N/A
		N/A	Flare Slope L	LT (%) N/A	N/A	Flare Slope RT (%)	N/A
		N/A	Flare Travers	sable LT? N/A	N/A	Flare Traversable RT?	N/A
	2	N/A	Landing Leng	gth (in) N/A	N/A	DWS Provided?	N/A
ALL DECULIOUCHADE	Surveyor Notes:	N/A	Landing Widt	th (in) N/A	N/A	DWS Contrast?	N/A
	N/A	N/A	Landing Slop	e (%) N/A	N/A	DWS Length (in)	N/A
		N/A	Landing X Sl	ope (%) N/A	N/A	DWS Full Width?	N/A
		N/A	Landing Curb	o? (Y/N) N/A	N/A	DWS Offset (in)	N/A
		N/A	Shared Land	ing? N/A			
the contract of the second sec	PROW/ADA:	N/A	Gutter Pondi	ng? N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.2.2	N/A	Gutter Lip Ht	(in) N/A	N/A	Gutter X Slope (%)	N/A
		N/A	Painted X Wa	alk1? Yes	N/A	Painted X Walk2?	N/A
			X Walk 1 Dire	ection To SE		X Walk 2 Direction	N/A
G B		N/A	X Walk 1 Wid	1122.0 th (in)	N/A	X Walk 2 Width (in)	N/A
Street 1 Name E MCCULLOUGH DR			X Walk 1 Slo	pe (%) 1.2		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2 StopSign			X Walk 1 X S	ilope (%) 0.3		X Walk 2 X Slope (%)	N/A
Street 2 Name N/A		N/A	Ramp inside	XWalk1? Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 N/A			Road Slope ((%) N/A	N/A	Clear Space?	N/A
			Road X Slope	e (%) N/A	N/A	Clear Space to XWalk (in)	N/A
		N/A	Any Obstruct	tions? N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 1	850.00	Obstruction 1	Гуре		Storm Grate/Utility Type	
				N/A			N/A

Yes Surface Condition? (G/P)

Good

