

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

54.0

59.0

12.9

2.2

6.8

6.7

N/A

Good

35.1

Main Street: ROBINSON_CHURCH_RD Cross Street: TEANECK PL Location: Intersection ID: 12114 NE Initial Pass/Fail: Fail **Overall Compliance: No** ADA ID: ED4A80311338 Ramp Type: Combination2 **Severity Score:** 37.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

No

Yes

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Surface Condition? (G/P)

Curb Slope (%)

Ramp Slope (%)

Ramp XSlope (%)

Data

45.5

57.5

2.8 No

3.9

28.5

48.0 No

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Ramp XSlope LT (%)



Street 1 Name None Stop Condition-Street 1 **ROBINSON CHURCH RD** N/A Street 2 Name Stop Condition-Street 2 N/A Possible Solutions: Compliance Description Remove & Replace Entire Ramp. N/A N/A N/A N/A N/A Yes Surveyor Notes: N/A DAMAGED CURB, LT RP < 5% N/A N/A N/A N/A PROW/ADA: N/A Not Found, R304.5.3, R304.3.2 N/A N/A N/A N/A N/A N/A

Total Cost:



N/A

1600.00

١.	Flare Type LT	N/A	N/A	Flare Type RT	N/A
١.	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
١.	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
١.	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
١.	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
١.	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
١.	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
١.	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
١.	Shared Landing?	N/A			
١.	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
١.	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To S		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	4.0		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	2.7		X Walk 2 X Slope (%)	N/A
١.	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A		Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstruction?	N/A
				Obstruction Type	
					N/A
			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	
	aller of the second				

Yes

