

Intersection ID: 10022434		Main Street: CANDLEWYCK_LN		Cross Street: N/A		Location:		NE	
ADA ID: EE4E04DFF256		Ramp Type: PerpDiag		Initial Pass/Fail: Pass		Overall Compliance: No		Severity Score: 27.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance		Description		Data	
		Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)	34.5	Yes	Ramp Slope (%)	5.3
				Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	2.0
				N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	1.3	Yes	Flare Slope RT (%)	2.5
				N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	Yes
				No	Landing Length (in)	N/A	Yes	DWS Provided?	Yes
				No	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes
				No	Landing Slope (%)	N/A	Yes	DWS Length (in)	24.0
				No	Landing X Slope (%)	N/A	No	DWS Full Width?	No
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.5.3, R305.1.4, R305.2, R302.7.2</p>				N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	6.5
				N/A	Shared Landing?	No			
				Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.8
				No	Gutter Lip Ht (in)	1.0	Yes	Gutter X Slope (%)	1.5
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To W		X Walk 2 Direction	To S
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	0.8		X Walk 2 Slope (%)	6.0
					X Walk 1 X Slope (%)	1.4		X Walk 2 X Slope (%)	0.7
				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
<p>Street 1 Name</p> <p>ENTRANCE</p> <p>Stop Condition-Street 2</p> <p>StopSign</p> <p>Street 2 Name</p> <p>CANDLEWYCK LN</p> <p>Stop Condition-Street 1</p> <p>None</p>					Road Slope (%)	1.0	N/A	Clear Space?	Yes
					Road X Slope (%)	0.6	N/A	Clear Space to XWalk (in)	N/A
				Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
					Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
						Yes	Surface Condition? (G/P)	Good	

