

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/AMain Street: ROGALLA_DRCross Street: N/ALocation:NADA ID: EE979A890B85Ramp Type: PerpInitial Pass/Fail: PassOverall Compliance: NoSeverity Score:15

Codes/Mitigation Info/Possible Solution



Street 1 Name ROGALLA DR
Stop Condition-Street 2 None
Street 2 Name N/A
Stop Condition-Street 1 N/A

/Possible Solution	
Possible Solutions:	Cor
Remove & Replace Entire Ramp.	N/A
Remove & Replace Gutter.	Yes
	N/A
	N/A
	N/A
	Yes
Surveyor Notes:	Yes
N/A	No
	Yes
	N/A
	N/A
PROW/ADA:	Yes
R304.2.2-Perp, R304.3.2-Para, R305,	Yes
R304.5.4, R304.5.3	N/A
	N/A
	N/A

Total Cost:	\$ 2600.00

Field Measurements/Component Compliance						
Compl	iance Description	Data	Comp	liance Description	Data	
N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	7.1	
Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.6	
N/A	Flare Type LT	None	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
Yes	Landing Length (in)	60.0	No	DWS Provided?	No	
Yes	Landing Width (in)	48.0	N/A	DWS Contrast?	No	
No	Landing Slope (%)	2.8	N/A	DWS Length (in)	N/A	
Yes	Landing X Slope (%)	0.4	N/A	DWS Full Width?	No	
N/A	Landing Curb? (Y/N)	No	N/A	DWS Offset (in)	N/A	
N/A	Shared Landing?	No				
Yes	Gutter Ponding?	No	No	Gutter Slope (%)	5.9	
Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	2.3	
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	X Walk 1 Direction	To S		X Walk 2 Direction	N/A	
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	2.7		X Walk 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	1.4		X Walk 2 X Slope (%)	N/A	
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	N/A	N/A	Clear Space?	Yes	
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No	
	Obstruction Type			Storm Grate/Utility Type		
		N/A			N/A	
			Yes	Surface Condition? (G/P)	Good	





