## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

6.5

Intersection ID: N/A Main St	n ID: N/A Main Street: AIRPORT_DR Cross Street: ASHLEY_CRES					Location:	NE	
			Initial Pass/Fail: Fail Overall Compliance: No					
						21.25		
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:	Com	Compliance Description Da		a Compliance Description		Data	
	Remove & Replace Curb Ramp Wit Two New Directional Ramps or Equivalent.	/ith N/A	Ramp Length (in)	59.0	Yes	BlendTrans Slope (%)	4.0	
		No	Ramp Width (in)	47.0	No	BlendTrans XSlope (%)	5.6	
		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	k .	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	1	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
		N/A	Shared Landing?	N/A				
	PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Not Found, R304.5.1, R304.5.3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
			X Walk 1 Direction	То W		X Walk 2 Direction	N/A	
	9		X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name AIRPORT DR	_		X Walk 1 Slope (%)	3.5		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 1 None			X Walk 1 X Slope (%)	5.0		X Walk 2 X Slope (%)	N/A	
Street 2 Name N/A		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 2 N/A			Road Slope (%)	5.0		Clear Space?	N/A	
			Road X Slope (%)	3.5	N/A	Clear Space to XWalk (in)	N/A	
		N/A	Any Obstructions?		N/A	Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$ 320	00.00	Obstruction Type			Storm Grate/Utility Type		
			<i>,</i> ,	N/A		, ,,,	N/A	



