

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 8380	Main St	Cross Street: TENNESSEE AV					Location: S		
ADA ID: EF211344EE9B	344EE9B Ramp Type: Perp		Initial Pass/Fail: Fail Overall Compliance:				nce: N	o Severity Score:	8.75
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	18 145	Possible Solutions:	<u>(</u>	Compliance Description Data Compliance Des			liance Description	Data	
	1 19 4	Remove & Replace Entire Ramp.	Ν	N/A	Ramp Length (in)	59.0	Yes	Ramp Slope (%)	5.2
	11/2			lo	Ramp Width (in)	46.5	Yes	Ramp XSlope (%)	0.4
	1		Ν	I/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	1		Ν	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
6./ ·	CH. C.	2	Ν	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	S BALLY		Ν	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:	Ν	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	Con.	N/A	Ν	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
8	M. Park		Ν	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
And the second	15		Ν	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	11		Ν	N/A	Shared Landing?	N/A			
the second is second	11	PROW/ADA:	Ν	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1	Ν	I/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			Ν	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
11 martin branches					X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
·/ ···································			Ν	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	CENTRE ST				X Walk 1 Slope (%)	5.8		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	3.1		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		N	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			١	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 1	850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A