cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 22621	Main St	Main Street: SHARON RD		Cross Street: GREENCASTLE DR				Location:	S
ADA ID: EF2D1F512AD3 Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Compliance: No					37.5		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
CREENCASTURE DR	a second	Possible Solutions:		Compliance Description		Data Compliance Description		liance Description	Data
	* *	Remove & Replace Curb Ramp V	Vith	N/A	Ramp Length (in)	60.0	No	Ramp Slope (%)	10.2
		Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	7.7
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
the 7	at the P			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		99 - 2020		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	1 44			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Star Star	the states	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	(CEE	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	AND A			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
No 1 States	Top .			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	1 te	4		N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N PAR A		· · ·		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
MAK A T			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name GREE	ENCASTLE DR				X Walk 1 Slope (%)	0.7		X Walk 2 Slope (%)	5.8
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	5.6		X Walk 2 X Slope (%)	0.6
Street 2 Name	SHARON RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	4.1	N/A	Clear Space?	N/A
					Road X Slope (%)	4.4	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

