

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A Main Street: S ALEXANDER ST Cross Street: E 4TH ST Location: **Overall Compliance: No ADA ID: EF40267D4A4C** Ramp Type: PerpDiag Initial Pass/Fail: Fail Severity Score: 21.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



E 4TH ST Street 1 Name Stop Condition-Street 2 None Street 2 Name **S ALEXANDER ST** Stop Condition-Street 1 StopSign **Remove & Replace Curb Ramp With Two New Directional Ramps or** Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.2.2

Total Cost: 3200.00

| Compliance Description [| | Data | Comp | oliance Description | Data |
|--------------------------|-----------------------|-------|------|-----------------------------|-------|
| N/A | Ramp Length (in) | 80.5 | No | Ramp Slope (%) | 11.9 |
| No | Ramp Width (in) | 39.0 | Yes | Ramp XSlope (%) | 0.7 |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| N/A | Flare Traversable LT? | No | N/A | Flare Traversable RT? | No |
| N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| N/A | Shared Landing? | N/A | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | Yes |
| | X Walk 1 Direction | To SW | | X Walk 2 Direction | To SE |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | 106.0 |
| | X Walk 1 Slope (%) | 2.8 | | X Walk 2 Slope (%) | 0.2 |
| | X Walk 1 X Slope (%) | 0.2 | | X Walk 2 X Slope (%) | 2.0 |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | Yes |
| | Road Slope (%) | 2.3 | N/A | Clear Space? | N/A |
| | Road X Slope (%) | 2.6 | N/A | Clear Space to XWalk (in) | N/A |
| N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | Obstruction Type | | | Storm Grate/Utility Type | |
| | | N/A | | | N/A |
| | | | Yes | Surface Condition? (G/P) | Good |





