

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

13.0

8.1

N/A

No

To N

N/A

5.4

1.2

N/A

N/A

N/A

N/A

N/A

Good

Intersection ID: 10022558 Main Street: CARMEL COMMONS BV Cross Street: N/A SW Location: Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** ADA ID: EFF3E2F13C33 Ramp Type: PerpDiag 67.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

No

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Flare Traversable RT?

Data

59.0

33.0

N/A

No

To E

N/A

4.2

5.4

N/A

3.3

7.2

N/A

N/A



CARMEL COMMONS BV Street 1 Name Stop Condition-Street 2 None **ENTRANCE** Street 2 Name Stop Condition-Street 1 StopSign Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes:

PROW/ADA:

N/A

Not Found, R304.5.1, R304.2.2, R304.5.3

n.	IN/A	
	No	
	N/A	

N/A

Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Gutter Ponding?

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (in)

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)

Road X Slope (%)

Any Obstructions?

Obstruction Type

Flare Traversable LT?

Flare Type LT



3200.00





Total Cost:

