

Access Compliance Report Public Rights-of-Way (Curb Ramps)



		(-			- /					
Intersection ID: 52288	Main Street: STEELE_CREEK_RD			Cross	Street:	DIXIE_RIVER_RD	Location:	S		
ADA ID: F0036FF1221D	Ramp Ty	Ramp Type: Combination2			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	25
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance										
		Possible Solutions:			Comp	liance Description	Data	Comp	liance Description	Data
200	JE.	Remove & Replace Entire	Ramp	_	N/A	Ramp Length LT (in)	58.0	N/A	Ramp Length RT (in)	N/A
	No. 1. 5				N/A	Ramp Width LT (in)	96.0	N/A	Ramp Width RT (in)	N/A
e e					N/A	Ramp Slope LT (%)	1.3	N/A	Ramp Slope RT (%)	N/A
	RA SING				N/A	Ramp XSlope LT (%)	5.6	N/A	Ramp XSlope RT (%)	N/A
G	TO A				N/A	Ramp Length (in)	95.0	No	Ramp Slope (%)	11.9
5	6				Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.5
	12	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
K Start	5. 64	LT RP < 5%			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	in the second				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
A BUILLAN NO	100				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	1 Barrow				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
ST TOPE TO	A CAN	R304.2.2, R304.5.3			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	11. 1 A m	,			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	11 5 10				N/A	Shared Landing?	N/A			
A A MARKEN AND					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	Signal				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	STEELE CREEK RD				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
Street 2 Name	N/A					X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	113.0		X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	2.5		X Walk 2 Slope (%)	N/A
						X Walk 1 X Slope (%)	1.7		X Walk 2 X Slope (%)	N/A
		Total Cost:	\$ 1	600.00	N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)	N/A		Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
		AVERITT EXPHESS		and the		and the second sec		N/A	Any Obstruction?	N/A
	helene and	**		- A		A CERT			Obstruction Type	

N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A

N/A

Yes	Surface Condition? (G/P)	Good
	Curb Slope (%)	3.4



