


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 31671	Main Street: EAVES_LN	Cross Street: PHIL_ONEIL_DR	Location: NE
ADA ID: F01636ECE78D	Ramp Type: Combination1	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 33.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length LT (in)	57.0	N/A	Ramp Length RT (in)	54.0
			No	Ramp Width LT (in)	47.0	Yes	Ramp Width RT (in)	48.0
			Yes	Ramp Slope LT (%)	0.1	No	Ramp Slope RT (%)	8.5
			Yes	Ramp XSlope LT (%)	0.7	No	Ramp XSlope RT (%)	2.5
			N/A	Ramp Length (in)	41.0	No	Ramp Slope (%)	9.2
			Yes	Ramp Width (in)	50.0	No	Ramp XSlope (%)	5.4
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
<p>Surveyor Notes:</p> <p>LT RP < 5%</p> <p>PROW/ADA:</p> <p>R304.5.1, R304.2.2, R304.5.3, R304.3.2</p>			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A			
			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
				X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
			X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
			X Walk 1 Slope (%)	2.5		X Walk 2 Slope (%)	N/A	
			X Walk 1 X Slope (%)	2.4		X Walk 2 X Slope (%)	N/A	
			Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
			Road Slope (%)	N/A		Clear Space?	N/A	
			Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstruction?	N/A	
						Obstruction Type	N/A	
								N/A
						N/A	Storm Grate/Utility Hazard?	N/A
							Storm Grate/Utility Type	N/A
								N/A
						Yes	Surface Condition? (G/P)	Good
							Curb Slope (%)	3.3

Street 1 Name

Stop Condition-Street 1

Street 2 Name

Stop Condition-Street 2

None

EAVES LN

N/A

N/A

Total Cost:

\$

1800.00

