

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

31.0

48.0

9.0

3.9

14.7

5.4

N/A

No

N/A

0.1

6.0

To SW

Intersection ID: 45500 Main Street: GRASSY CROPS RD Cross Street: TRIPLE OAK RD Ε Location: **Overall Compliance: No Severity Score:** 0 ADA ID: F03F5DCD4AE1 Ramp Type: Combination1Diag Initial Pass/Fail: Fail

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

No

No

Nο

No

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Flare Traversable RT?

Ramp XSlope RT (%)

Data

48.0

48.0

8.2

3.8

70.0

30.0

N/A

No

N/A

7.4

4.9

To NW



Street 1 Name Stop Condition-Street 1 Street 2 Name Stop Condition-Street 2

StopSign TRIPLE OAK RD None **GRASSY CROPS RD** Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.2.2, R304.5.3, R304.3.2

Total Cost:



X Walk 1 Slope (%)

X Walk 1 X Slope (%)



N/A N/A 3200.00 N/A Ramp inside XWalk1? Ramp inside XWalk2? N/A Road Slope (%) 5.7 Clear Space? N/A Road X Slope (%) 2.6 N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good 11.1 Curb Slope (%)



