

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: MACKINAC_ST Cross Street: OLD_TIMBER_RD Location: Intersection ID: 3161

ADA ID: F0472E630DA	B Ramp Ty	/pe: Directional1	Initial	Pass/F	ail: Fail Overall	Complian	ce: N	o Severity Score:	13.75	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:		Comp	oliance Description	Data	Comp	liance Description	Data	
		Remove & Replace Entire Ra	ımp.	N/A	Ramp Length (in)	75.0	N/A	Grade Break?	N/A	
		·	-	Yes	Ramp Width (in)	48.5	N/A	Grade Break Slope (%)	0.0	
				No	Ramp Slope (%)	8.4	N/A	Grade Break XSlope (%)	0.0	
				Yes	Ramp XSlope (%)	2.1				
	9/			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
<u>6</u>				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
(5.)	ā	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
/ `	18			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
	THE SERVICE SE	R304.2.2		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
	\			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
	1			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No		Road Slope (%)	1.0	
Street 1 Name	OLD TIMBER RD				X Walk 1 Direction	To NW		Road X Slope (%)	4.3	
Stop Condition-Street 1	None				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	1.0	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	4.3	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	16.1	





