

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10033959 Main Street: PARK_RD Cross Street: N/A Location: SE **Overall Compliance: No ADA ID: F052DA27E13D** Ramp Type: Perp Initial Pass/Fail: Fail Severity Score: 13.75

Codes/Mitigation Info/Possible Solution



Street 1 Name	PARK RD
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: N/A PROW/ADA: Not Found, R304.2.2, R304.5.3

V. V. V. State Sta	
The state of the s	
	Ε
	5
The state of the s	
The second secon	

Total Cost:



1850.00

Field Measurements/Component Compliance								
Comp	liance Description	Data	Comp	liance	Description	Data		
N/A	Ramp Length (in)	59.0	No	Ramp	Slope (%)	9.8		
Yes	Ramp Width (in)	48.0	No	Ramp	XSlope (%)	3.6		
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A		
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A		
N/A	Painted X Walk1?	Yes	N/A	Paint	ed X Walk2?	N/A		
	X Walk 1 Direction	To NW		X Wa	lk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	101.0	N/A	X Wa	lk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	2.0		X Wa	lk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	2.1		X Wa	lk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp	inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm	n Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm	n Grate/Utility Type			
		N/A				N/A		
			Yes	Surfa	ce Condition? (G/P)	Good		