

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 25815	Main Street: REA RD			Cross Street: PINEVILLE-MATTHEWS_RD				Location:	NW	
ADA ID: F05F87647F47 Ramp Type: Perp			initia	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	21.25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description D			ta Compliance Description		Data	
	1 2 2 3	Remove & Replace Entire Ram	ıp.	N/A	Ramp Length (in)	70.0	No	Ramp Slope (%)	10.2	
	A DANS			No	Ramp Width (in)	47.5	Yes	Ramp XSlope (%)	1.2	
	The second			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	ALL LAND			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	C. C. Ann			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	A strategy	-		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
e e e e e e e e e e e e e e e e e e e	L.	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	the second	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		5°		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	-11-	-		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	EL			N/A	Shared Landing?	N/A				
the second se	J.D.	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
AND	H	R304.5.1, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
RIVENUS				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
	140				X Walk 1 Direction	To E		X Walk 2 Direction	N/A	
E	n atta	2		N/A	X Walk 1 Width (in)	112.0	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	REA RD				X Walk 1 Slope (%)	1.1		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

**Yes** Surface Condition? (G/P)

Good

