

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

57.0

47.5

3.4

6.7

7.5

2.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

0.8

Intersection ID: N/A Main Street: FIRST RUN CT Cross Street: PAPER BIRCH DR SE Location: **Overall Compliance: No Severity Score:** 0 ADA ID: F0D7431D8F46 Ramp Type: Combination2Diag Initial Pass/Fail: Fail

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

No

Yes

No

Yes

Yes

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

Curb Slope (%)

Flare Traversable RT?

Ramp XSlope RT (%)

Data

50.5

47.5

5.5

4.9

83.5

36.5

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)



Street 1 Name StopSign Stop Condition-Street 1 **FIRST RUN CT** Street 2 Name None Stop Condition-Street 2 PAPER BIRCH DR

Compliance Description Possible Solutions: N/A Remove & Replace Curb Ramp With Two New Directional Ramps or No Equivalent. Yes No N/A No Surveyor Notes: N/A N/A N/A N/A N/A N/A PROW/ADA: N/A R304.5.1, R304.5.1, R304.5.3 N/A N/A N/A N/A N/A N/A



3200.00

N/A

Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A Shared Landing? N/A Gutter Ponding? N/A N/A Gutter Slope (%) N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No Painted X Walk2? No To N To W X Walk 1 Direction X Walk 2 Direction X Walk 1 Width (in) N/A X Walk 2 Width (in) N/A 3.2 X Walk 1 Slope (%) X Walk 2 Slope (%) 3.8 X Walk 1 X Slope (%) 0.9 X Walk 2 X Slope (%) 2.5 N/A Ramp inside XWalk1? N/A Ramp inside XWalk2? N/A Road Slope (%) 1.6 Clear Space? N/A Road X Slope (%) 3.7 N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good





Total Cost: