cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



			•	- /					
Intersection ID: 50637	Main Stre	eet: RED_WATER_R	Cross Street: TOM_SHORT_RD			Location:		SW	
ADA ID: F1379967E9AE	Ramp Ty	Ramp Type: Combination1			Initial Pass/Fail: Fail Overall Complian			nce: No Severity Score:	
Coc	des/Mitigation Info/	Possible Solution			Field Measure	ements/Co	ompo	nent Compliance	
		Possible Solutions:		Compliance Description		Data Compliance Description			Data
Ly P . All		Remove & Replace Enti	e Entire Ramp.	N/A	Ramp Length LT (in)	38.0	N/A	Ramp Length RT (in)	42.0
A L. Ab.			•	Yes	Ramp Width LT (in)	60.0	Yes	Ramp Width RT (in)	60.0
and a state	· / / ////			Yes	Ramp Slope LT (%)	3.2	No	Ramp Slope RT (%)	11.6
6.	1 1 Berlina			Yes	Ramp XSlope LT (%)	1.1	Yes	Ramp XSlope RT (%)	0.4
RED WATER PD	1 M. Carriero			N/A	Ramp Length (in)	25.0	No	Ramp Slope (%)	10.3
				Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.6
		Surveyor Notes:		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		LT RP < 5%		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		PROW/ADA:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		Not Found, R304.2	2, R304.5.3,	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	12 72 2017	R304.3.2		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	A THELES			N/A	Shared Landing?	N/A			
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	None			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	TOM SHORT RD			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
Street 2 Name	N/A				X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
Stop Condition-Street 2	N/A				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	2.0		X Walk 2 Slope (%)	N/A
					X Walk 1 X Slope (%)	2.0		X Walk 2 X Slope (%)	N/A
		Total Cost:	\$ 180	0.00 N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
					Road Slope (%)	N/A		Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				States	and the second se		N/A	Any Obstruction?	N/A
		at and the second second						Obstruction Type	
		and an and a second second			and and a second				N/A
	-						N/A	Storm Grate/Utility Hazard?	N/A
					i.			Storm Grate/Utility Type	
			/						N/A

 Yes
 Surface Condition? (G/P)
 Good

 Curb Slope (%)
 10.8