

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 13060	Main Street: DUNKIRK_DR	Cross Street: SPRUCE_ST	Location: SW
ADA ID: F144AB98F42E	Ramp Type: ParaDiag	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 15	

#### Codes/Mitigation Info/Possible Solution

#### Field Measurements/Component Compliance



Possible Solutions:

**Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.**

Surveyor Notes:

**DWS NAILS EXPOSED**

PROW/ADA:

**R304.2.1, R305, R304.5.4**

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	41.0	N/A	Ramp Length RT (in)	N/A
Yes	Ramp Width LT (in)	108.0	N/A	Ramp Width RT (in)	N/A
Yes	Ramp Slope LT (%)	5.7	N/A	Ramp Slope RT (%)	N/A
Yes	Ramp XSlope LT (%)	1.7	N/A	Ramp XSlope RT (%)	N/A
Yes	Landing Length (in)	108.0	No	DWS Provided?	No
No	Landing Width (in)	34.0	N/A	DWS Contrast?	No
Yes	Landing Slope (%)	1.8	N/A	DWS Length (in)	N/A
Yes	Landing X Slope (%)	0.3	N/A	DWS Full Width?	No
N/A	Landing Curb? (Y/N)	No	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	No			
Yes	Gutter Ponding?	No	No	Gutter Slope (%)	5.8
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.0
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	3.0		X Walk 2 Slope (%)	3.0
	X Walk 1 X Slope (%)	2.0		X Walk 2 X Slope (%)	0.6
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	1.6	N/A	Clear Space?	Yes
	Road X Slope (%)	7.0	N/A	Clear Space to XWalk (in)	N/A
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	17.0

Total Cost: \$ 3950.00

