

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 29173 Main Street: CHIEFTAIN_DR Cro					ross Street: GRANSTARK_CT				Location:	SW
ADA ID: F1786438A964	64 Ramp Type: BlendTrans1			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	33.75
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:			Compliance Description		Data Compliand		nce Description	Data
		Remove & Replace Cu Two New Directional R	b Ramp	With	N/A	Ramp Length (in)	45.5	Yes	BlendTrans Slope (%)	3.8
					No	Ramp Width (in)	41.0	No	BlendTrans XSlope (%)	7.3
		Equivalent.			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
The second secon					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
ANTERIA	A	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the second second		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	R				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	B				N/A	Shared Landing?	N/A			
C.L. T.T.		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	G C	Not Found, R304.5.1, R	304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	A BER				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To E		X Walk 2 Direction	N/A	
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name	GRANSTARK CT					X Walk 1 Slope (%)	4.2		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	StopSign					X Walk 1 X Slope (%)	5.6		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A					Road Slope (%)	5.6		Clear Space?	N/A
						Road X Slope (%)	4.2	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

6.1