


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10365	Main Street: N_CHURCH_ST	Cross Street: W_24TH_ST	Location:	E
ADA ID: F1A66E421FE0	Ramp Type: Combination1	Initial Pass/Fail: Pass	Overall Compliance: No	Severity Score: 0.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	Possible Solutions:		Remove & Replace Entire Ramp.						
			Remove & Replace Sidewalk.						
			Remove & Replace Gutter.						
	Surveyor Notes:								
	GTR GAP 1.5", RT RP < 5%								
	PROW/ADA:								
	Not Found, R304.5.3, R304.2.1, R304.2.2-Perp, R304.3.2-Para								
	Total Cost:		\$	2950.00					