


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 17544	Main Street: MANHASSET_RD	Cross Street: MURRAYHILL_RD	Location: NW
ADA ID: F1F14EA0357F	Ramp Type: ParaDiag	Initial Pass/Fail: Fail	Overall Compliance: No
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

	Possible Solutions:			
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.			
	Surveyor Notes:			
	LT RP < 5%			
	PROW/ADA:			
	R304.5.1, R304.3.2			
Street 1 Name	MANHASSET RD			
Stop Condition-Street 1	StopSign			
Street 2 Name	MURRAYHILL RD			
Stop Condition-Street 2	None			
Total Cost:		\$	3200.00	

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	20.0	N/A	Ramp Length RT (in)	97.0
Yes	Ramp Width LT (in)	79.0	No	Ramp Width RT (in)	47.0
Yes	Ramp Slope LT (%)	4.4	No	Ramp Slope RT (%)	14.0
Yes	Ramp XSlope LT (%)	2.0	Yes	Ramp XSlope RT (%)	0.7
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To S		X Walk 2 Direction	To E
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	3.6		X Walk 2 Slope (%)	5.3
	X Walk 1 X Slope (%)	6.8		X Walk 2 X Slope (%)	4.5
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	7.4	N/A	Clear Space?	N/A
	Road X Slope (%)	5.7	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	N/A

