

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

9.5

8.0

N/A

No

To E

N/A

3.2

1.5

N/A

N/A

N/A

N/A

N/A

Good

Intersection ID: 43967 Main Street: BEAM RD Cross Street: CARRINGTON OAKS DR Location: NW **Severity Score: ADA ID: F26A3F7D1DEA** Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No** 12.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

Compliance Description

Ramp Slope (%)

Storm Grate/Utility Type

Surface Condition? (G/P)

<u>Data</u>

45.0



CARRINGTON OAKS DR Street 1 Name Stop Condition-Street 2 StopSign **BEAM RD** Street 2 Name Stop Condition-Street 1 None Possible Solutions: Compliance Description Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.2.2

N/A Ramp Length (in) Yes N/A N/A

3200.00

Yes Ramp XSlope (%) Ramp Width (in) 48.0 N/A Flare Type LT N/A Flare Type RT N/A N/A Flare Slope RT (%) Flare Slope LT (%) Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A **DWS Provided?** Landing Length (in) Landing Width (in) N/A N/A **DWS Contrast?** N/A Landing Slope (%) N/A DWS Length (in) Landing X Slope (%) N/A N/A DWS Full Width? Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A Shared Landing? **Gutter Ponding?** N/A N/A Gutter Slope (%) Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) Painted X Walk1? No N/A Painted X Walk2? X Walk 1 Direction To S X Walk 2 Direction N/A X Walk 1 Width (in) X Walk 2 Width (in) X Walk 1 Slope (%) 5.2 X Walk 2 Slope (%) X Walk 2 X Slope (%) X Walk 1 X Slope (%) 3.6 N/A N/A Ramp inside XWalk2? Ramp inside XWalk1? Road Slope (%) 0.6 N/A Clear Space? N/A Road X Slope (%) 4.8 Clear Space to XWalk (in) N/A N/A Any Obstructions? Storm Grate/Utility Hazard?

N/A

Yes





Total Cost:



Obstruction Type