cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 8283	Main Street: DRURY_DR				Street:	W_CRAIGHEAD_RD	Location:	SE			
ADA ID: F279F2A3F98D	Ramp Type: Combination1			Initial	Initial Pass/Fail: Fail Overall Com			ce: N	o Severity Score:	10	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
H - MIL WAR	1	Possible Solutions:			Compliance Description		Data Compliance Description		Data		
The second second	2 Jan 7	Remove & Repla	ace Entire Ram	p .	N/A	Ramp Length LT (in)	30.0	N/A	Ramp Length RT (in)	33.0	
	Kr and some			•	Yes	Ramp Width LT (in)	59.0	Yes	Ramp Width RT (in)	63.0	
	1.1.1				Yes	Ramp Slope LT (%)	5.5	Yes	Ramp Slope RT (%)	0.4	
	A STATE				Yes	Ramp XSlope LT (%)	1.5	No	Ramp XSlope RT (%)	2.5	
W @Da	1				N/A	Ramp Length (in)	42.0	Yes	Ramp Slope (%)	6.8	
CONSTRUCTION OF	Bar X				No	Ramp Width (in)	47.5	Yes	Ramp XSlope (%)	1.5	
		Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	ale-	RT RP < 5%			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
The LA LAND	AMAL 1				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
5 State 1	1 21				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	FR Man Start				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
SCONTAN E	- MA	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		Not Found, R304.5.1, R304.5.3			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
	a de der				N/A	Shared Landing?	N/A				
	A A A A				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	StopSign				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	DRURY RD				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
Street 2 Name	N/A					X Walk 1 Direction	To W		X Walk 2 Direction	N/A	
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	0.1		X Walk 2 Slope (%)	N/A	
						X Walk 1 X Slope (%)	1.9		X Walk 2 X Slope (%)	N/A	
		Total Cost:	\$	1800.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	N/A		Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				A State	- Martin			N/A	Any Obstruction?	N/A	
		the galant		The second	-				Obstruction Type		

- N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A
- Yes
 Surface Condition? (G/P)
 Good

 Curb Slope (%)
 31.7





