

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

66.0

70.0

8.0

1.8

8.7

1.5

N/A

Intersection ID: 17190 Main Street: MURRAYHILL RD Cross Street: SCALEYBARK RD Location: N **Overall Compliance: No Severity Score:** ADA ID: F27E1AF4A6C6 Ramp Type: Combination1 Initial Pass/Fail: Fail 12.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

Yes

Yes

Nο

Yes

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Flare Traversable RT?

Ramp XSlope RT (%)

Data

67.0

70.0

8.4

1.9

70.0

59.0

N/A

No

N/A

5.0

0.9

N/A

To SW



Street 1 Name None Stop Condition-Street 1 SCALEYBARK RD N/A Street 2 Name Stop Condition-Street 2 N/A Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: N/A PROW/ADA: Not Found, R304.2.2, R304.3.2

Total Cost:





N/A

Ramp inside XWalk1?

1800.00

F	Road Slope (%)	N/A		Clear Space?	N/A
F	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
A CONTRACTOR OF THE PARTY OF TH	2 2		N/A	Any Obstruction?	N/A
V V				Obstruction Type	
					N/A
			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	
	and the same of th				N/A
			Yes	Surface Condition? (G/P)	Good
				Curb Slope (%)	13.9



