## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 46819 Main Street: CLAUDE_FREEMAN_DR Cross Street: AZALEA_HILLS_DR								Location:	NW
ADA ID: F28E49A08A87 Ramp Type: PerpDiag			Initial I	nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	31.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data	Data Compliance Description		Data
		Remove & Replace Curb Ramp V	Vith	N/A	Ramp Length (in)	46.0	No	Ramp Slope (%)	9.3
		Two New Directional Ramps or Equivalent.		No	Ramp Width (in)	34.5	No	Ramp XSlope (%)	2.8
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
Mat i Little				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
And the second s				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
19 1		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
Manuscher		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	HILLS DR			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
<u>6</u> <u>6</u>				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
TA DAR	A BOLER			N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	A AMA	R304.5.1, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	Jamila LT			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To S		X Walk 2 Direction	To E
ter as for			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	AZALEA HILLS DR				X Walk 1 Slope (%)	1.3		X Walk 2 Slope (%)	0.8
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.7		X Walk 2 X Slope (%)	1.1
Street 2 Name	CLAUDE FREEMAN DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	2.9	N/A	Clear Space?	N/A
					Road X Slope (%)	0.6	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P) Good

