

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 47974 Main Street: TOM_SHORT_RD Cross Street: BRYANT_FARMS_RD Location: NW

ADA ID: F28F665A6459 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 21.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



The second secon	Committee of the Commit
Street 1 Name	TOM SHORT RD
Stop Condition-Street 2	None
Street 2 Name	N/A
Ston Condition-Street 1	N/A

Possible Solutions:	
Remove & Replace Entire Ramp.	١
	i
	ı
Surveyor Notes:	
N/A	i
N/A	ı
	ı
	ı
PROW/ADA:	ı
Not Found, R304.5.1, R304.2.2	ı
	ı
	ı

	12	10 M	A CONTRACTOR OF THE PARTY OF TH
	NINET.	L Z WAST	
6		Bellevice	and the second
1	1		

Total Cost:



1850.00



Compliance Description Data Compliance Description Data No N/A Ramp Length (in) 166.0 Ramp Slope (%) 10.4 Yes Ramp XSlope (%) No Ramp Width (in) 47.5 1.6 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A Flare Slope LT (%) N/A N/A Flare Slope RT (%) N/A N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A Landing Length (in) N/A N/A **DWS Provided?** N/A N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A N/A Landing Slope (%) DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A Gutter Ponding? N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No N/A Painted X Walk2? N/A X Walk 1 Direction To E X Walk 2 Direction N/A N/A X Walk 1 Width (in) N/A X Walk 2 Width (in) N/A X Walk 1 Slope (%) 3.6 X Walk 2 Slope (%) N/A X Walk 1 X Slope (%) 0.4 X Walk 2 X Slope (%) N/A N/A Ramp inside XWalk1? N/A N/A Ramp inside XWalk2? N/A Road Slope (%) N/A N/A Clear Space? N/A Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A Any Obstructions? N/A N/A N/A Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good