

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 13579	Main Street: S_MCDOWELL_ST	Cross Street: E_STONEWALL_ST	Location: NE
ADA ID: F2A9A317A63B	Ramp Type: Combination1	Initial Pass/Fail: Pass	Overall Compliance: No
			Severity Score: 10.25

Codes/Mitigation Info/Possible Solution	Field Measurements/Component Compliance
---	---



Possible Solutions:

**Remove & Replace Entire Ramp.  
Remove & Replace Gutter.**

Surveyor Notes:

**RT RP < 5%**

PROW/ADA:

**Not Found, R304.5.3, R304.2.1,  
R304.2.2-Perp, R304.3.2-Para**

Street 1 Name	Signal
Stop Condition-Street 1	S MCDOWELL ST
Street 2 Name	N/A
Stop Condition-Street 2	N/A

Total Cost: \$ 2550.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	53.0	N/A	Ramp Length RT (in)	52.0
Yes	Ramp Width LT (in)	60.0	Yes	Ramp Width RT (in)	93.0
Yes	Ramp Slope LT (%)	6.2	Yes	Ramp Slope RT (%)	1.0
No	Ramp XSlope LT (%)	3.2	No	Ramp XSlope RT (%)	3.5
N/A	Ramp Length (in)	108.0	Yes	Ramp Slope (%)	5.4
Yes	Ramp Width (in)	49.0	No	Ramp XSlope (%)	3.7
N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped
Yes	Flare Slope LT (%)	8.4	Yes	Flare Slope RT (%)	3.5
N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes
No	Landing Length (in)	N/A	Yes	DWS Provided?	Yes
No	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes
No	Landing Slope (%)	N/A	Yes	DWS Length (in)	25.0
No	Landing X Slope (%)	N/A	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	1.0
N/A	Shared Landing?	No			
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.3
Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	3.6
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	104.0		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	1.8		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	2.0		X Walk 2 X Slope (%)	N/A
Yes	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A		Clear Space?	Yes
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			Yes	Any Obstruction?	No
				Obstruction Type	N/A
			Yes	Storm Grate/Utility Hazard?	No
				Storm Grate/Utility Type	N/A
			Yes	Surface Condition? (G/P)	Good
				Curb Slope (%)	9.0

