cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 10140	Main Street: E_36TH_ST		Cross Street: N_ALEXANDER_ST			Location:	N
ADA ID: F2E0A88D6B5B	B5B Ramp Type: PerpDiag		Initial Pass/Fail: Pass Overall Compliance			o Severity Score:	0.25
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance				
0. 0	Possible Solutions:	Con	Compliance Description E		ta Compliance Description		Data
	Remove & Replace Curb Ramp	With N/A	Ramp Length (in)	96.0	Yes	Ramp Slope (%)	5.2
	Two New Directional Ramps or	Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	3.0
	Equivalent. Remove & Replace	N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
	Gutter.	N/A	Flare Slope LT (%)	-	Yes	Flare Slope RT (%)	1.2
		N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes
	The second se	Yes	Landing Length (in)	48.0	Yes	DWS Provided?	Yes
	Surveyor Notes:	Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes
ES STAT	N/A	Yes	Landing Slope (%)	0.3	Yes	DWS Length (in)	24.0
		Yes	Landing X Slope (%)	1.5	Yes	DWS Full Width?	Yes
	4 10	N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	5.0
G V W	alle.	N/A	Shared Landing?	No		. ,	
	PROW/ADA:	Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.2
SIII A DAY	Not Found, R304.5.3, R305.2	Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	5.5
Sold and a state		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes
	o f .		X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
		N/A	X Walk 1 Width (in)	110.0	N/A	X Walk 2 Width (in)	103.0
Street 1 Name	E 36TH ST		X Walk 1 Slope (%)	4.0		X Walk 2 Slope (%)	4.0
Stop Condition-Street 2	None		X Walk 1 X Slope (%)	1.6		X Walk 2 X Slope (%)	4.9
Street 2 Name NALEXA	ANDER ST	Yes	Ramp inside XWalk1?	Yes	Yes	Ramp inside XWalk2?	Yes
Stop Condition-Street 1	StopSign		Road Slope (%)		N/A	Clear Space?	Yes
			Road X Slope (%)	4.5	Yes	Clear Space to XWalk (in)	57.0
		Yes	,	No	Yes	Storm Grate/Utility Hazard?	No
	Total Cost: \$	3950.00	Obstruction Type			Storm Grate/Utility Type	
				N/A			N/A

