


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 11200	Main Street: MILTON_RD	Cross Street: VILLAGE_GREEN_DR	Location: SW
ADA ID: F34F8CD7AB25	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
Severity Score: 31.25			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

	Possible Solutions:				
	Remove & Replace Entire Ramp.				
	Surveyor Notes:				
	N/A				
	PROW/ADA:				
	Not Found, R304.5.1, R304.2.2, R304.5.3				
	Street 1 Name	VILLAGE GREEN DR			
	Stop Condition-Street 2	StopSign			
	Street 2 Name	N/A			
	Stop Condition-Street 1	N/A			
Total Cost:		\$	1850.00		
		Compliance	Description	Data	Compliance Description Data
		N/A	Ramp Length (in)	59.5	No Ramp Slope (%) 11.2
		No	Ramp Width (in)	34.0	No Ramp XSlope (%) 2.7
		N/A	Flare Type LT	N/A	N/A Flare Type RT N/A
		N/A	Flare Slope LT (%)	N/A	N/A Flare Slope RT (%) N/A
		N/A	Flare Traversable LT?	N/A	N/A Flare Traversable RT? N/A
		N/A	Landing Length (in)	N/A	N/A DWS Provided? N/A
		N/A	Landing Width (in)	N/A	N/A DWS Contrast? N/A
		N/A	Landing Slope (%)	N/A	N/A DWS Length (in) N/A
		N/A	Landing X Slope (%)	N/A	N/A DWS Full Width? N/A
		N/A	Landing Curb? (Y/N)	N/A	N/A DWS Offset (in) N/A
		N/A	Shared Landing?	N/A	
		N/A	Gutter Ponding?	N/A	N/A Gutter Slope (%) N/A
		N/A	Gutter Lip Ht (in)	N/A	N/A Gutter X Slope (%) N/A
		N/A	Painted X Walk1?	No	N/A Painted X Walk2? N/A
			X Walk 1 Direction	To E	X Walk 2 Direction N/A
		N/A	X Walk 1 Width (in)	N/A	N/A X Walk 2 Width (in) N/A
			X Walk 1 Slope (%)	1.1	X Walk 2 Slope (%) N/A
			X Walk 1 X Slope (%)	8.0	X Walk 2 X Slope (%) N/A
		N/A	Ramp inside XWalk1?	N/A	N/A Ramp inside XWalk2? N/A
			Road Slope (%)	N/A	N/A Clear Space? N/A
			Road X Slope (%)	N/A	N/A Clear Space to XWalk (in) N/A
		N/A	Any Obstructions?	N/A	N/A Storm Grate/Utility Hazard? N/A
			Obstruction Type		Storm Grate/Utility Type
				N/A	N/A
				Yes	Surface Condition? (G/P) Good

