

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A	ntareaction ID: N/A Main Street: CITY DADK DD				Croco Street: NATIONAL AV				NE	
		Main Street: CITY_PARK_DR		Cross Street: NATIONAL_AV				Location: o Severity Score:		
ADA ID: F35242F30792	Ramp Ty	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No				12.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	12	Possible Solutions:		Compliance Description			Data Compliance Description			
	1.2 SK	Remove & Replace Entire Ram	p.	N/A	Ramp Length (in)	82.0	N/A	Grade Break?	N/A	
				Yes	Ramp Width (in)	75.0	N/A	Grade Break Slope (%)	0.0	
	AL OF AL			Yes	Ramp Slope (%)	0.2	N/A	Grade Break XSlope (%)	0.0	
				No	Ramp XSlope (%)	5.6				
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
the terms				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
S. S		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
the state of the second		N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
6 ST				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
AN E				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
8				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
		R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
A A A A A A A A A A A A A A A A A A A				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
1 11	and the N			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
1-1-16 E	and the second second			N/A	Painted X Walk1?	Yes		Road Slope (%)	2.2	
Street 1 Name	CITY PARK DR				X Walk 1 Direction	To W		Road X Slope (%)	3.2	
Stop Condition-Street 1	None				X Walk 1 Width (in)	96.0		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	2.2	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	3.2	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	9.5	

