

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

11.7

1.8

Intersection ID: 14690 Main Street: LINGANORE PL **Cross Street: ROMANY RD** Location: NE **Overall Compliance: No** ADA ID: F3789A570ED0 Ramp Type: PerpDiag Initial Pass/Fail: Fail **Severity Score:** 12.5

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance

43.0 No

70.0 Yes

Ramp Length (in)

Ramp Width (in)

Data Compliance Description

Ramp Slope (%)

Ramp XSlope (%)



Possible Solutions: Compliance Description **Remove & Replace Curb Ramp With** N/A Two New Directional Ramps or Yes





		Equivalent.			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
2	44				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	444				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	The second second				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
NAME OF THE PARTY		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
ू <mark>है</mark>		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
ROMANY	RD .				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
The Bullion of					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	PART WAR				N/A	Shared Landing?	N/A			
A STATE OF THE PARTY OF THE PAR	A STATE OF THE STA	PROW/ADA:			N/A	Gutter Ponding?	Yes	N/A	Gutter Slope (%)	N/A
	Not Found, R304.2.2			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
		ŕ			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To W		X Walk 2 Direction	To S	
	是過程人一个				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	LINGANORE PL					X Walk 1 Slope (%)	5.4		X Walk 2 Slope (%)	1.7
Stop Condition-Street 2	StopSign					X Walk 1 X Slope (%)	3.5		X Walk 2 X Slope (%)	1.7
Street 2 Name	ROMANY RD				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None					Road Slope (%)	0.7	N/A	Clear Space?	N/A
						Road X Slope (%)	5.6	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A
								Yes	Surface Condition? (G/P)	Good
			1							