

# Access Compliance Report Public Rights-of-Way (Curb Ramps)

Intersection ID: 6750      Main Street: ATLAS\_DR      Cross Street: JUNIPERUS\_DR      Location: SE

ADA ID: F3838BD51A29      Ramp Type: BlendTrans2      Initial Pass/Fail: Fail      Overall Compliance: No      Severity Score: 1.25

**Codes/Mitigation Info/Possible Solution**      **Field Measurements/Component Compliance**



Possible Solutions:  
**Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.**

Surveyor Notes:  
**NO LT SW**

PROW/ADA:  
**R304.5.3**

Street 1 Name      **JUNIPERUS DR**  
Stop Condition-Street 1      **StopSign**  
Street 2 Name      **N/A**  
Stop Condition-Street 2      **N/A**

Total Cost:      \$      **3200.00**

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	96.0	Yes	BlendTrans Slope (%)	3.1
Yes	Ramp Width (in)	48.0	No	BlendTrans XSlope (%)	2.9
N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped
N/A	Flare Slope LT (%)	13.8	N/A	Flare Slope RT (%)	4.5
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	No
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	No
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	No
N/A	Landing Curb? (Y/N)	No	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	No			
N/A	Gutter Ponding?	No	N/A	Gutter Slope (%)	2.0
N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	2.0
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To N		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	3.0		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	3.0		Clear Space?	Yes
	Road X Slope (%)	1.9	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	No	N/A	Storm Grate/Utility Hazard?	No
	Obstruction Type			Storm Grate/Utility Type	
			N/A		N/A
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	N/A

