

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

69.0

N/A

N/A

Good

N/A

Intersection ID: 3180 Main Street: JOHNSTON OEHLER RD Cross Street: SONG SPARROW LN Location: **Overall Compliance: No** ADA ID: F3DC51791D2C Ramp Type: Combination1 Initial Pass/Fail: Fail **Severity Score:** 25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

53.0

Ramp Length LT (in)

N/A

Data Compliance Description

Ramp Length RT (in)



Street 1 Name None Stop Condition-Street 1 JOHNSTON OEHLER RD Street 2 Name N/A Stop Condition-Street 2 N/A

Possible Solutions: Compliance Description Remove & Replace Entire Ramp. N/A Surveyor Notes: N/A PROW/ADA: R304.2.2, R304.3.2



Total Cost:



1800.00

Yes	Ramp Width LT (in)	89.0	Yes	Ramp Width RT (in)	90.5
No	Ramp Slope LT (%)	10.2	No	Ramp Slope RT (%)	8.8
Yes	Ramp XSlope LT (%)	0.8	Yes	Ramp XSlope RT (%)	1.0
N/A	Ramp Length (in)	90.0	No	Ramp Slope (%)	12.1
Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.1
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	2.7		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A		Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstruction?	N/A
				Obstruction Type	
The state of the s					N/A

N/A

Yes

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Curb Slope (%)