

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

N/A

N/A

Good 13.8

Intersection ID: N/A Main Street: LYME_BROOK_LN Cross Street: SPRATT_ST Location: E

ADA ID: F3F4B1BA1F0A Ramp Type: Combination1Diag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 0

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

StopSign LYME BROOK LN None SPRATT ST Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.2.2, R304.5.3, R304.3.2



Total Cost:



3200.00

Compliance Description Data Compliance Description Data N/A N/A Ramp Length LT (in) 50.0 Ramp Length RT (in) 43.0 Yes Yes Ramp Width LT (in) 48.0 Ramp Width RT (in) 48.0 No Yes Ramp Slope LT (%) 7.3 Ramp Slope RT (%) 8.4 Ramp XSlope LT (%) 5.1 No Ramp XSlope RT (%) No 4.0 N/A Ramp Length (in) 58.5 Nο Ramp Slope (%) 9.7 35.0 No Ramp XSlope (%) No Ramp Width (in) 3.3 N/A Flare Type LT N/A N/A Flare Type RT N/A N/A N/A N/A Flare Slope LT (%) Flare Slope RT (%) N/A N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A Landing Length (in) N/A N/A DWS Provided? N/A N/A N/A N/A Landing Width (in) **DWS Contrast?** N/A N/A Landing Slope (%) N/A N/A DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A Shared Landing? N/A N/A Gutter Ponding? N/A N/A Gutter Slope (%) N/A N/A N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A N/A N/A Painted X Walk1? No Painted X Walk2? No To NW To SW X Walk 1 Direction X Walk 2 Direction X Walk 1 Width (in) N/A X Walk 2 Width (in) N/A 0.6 7.9 X Walk 1 Slope (%) X Walk 2 Slope (%) X Walk 1 X Slope (%) 3.6 X Walk 2 X Slope (%) 0.7 N/A N/A Ramp inside XWalk1? N/A Ramp inside XWalk2? N/A Road Slope (%) 6.7 Clear Space? N/A Road X Slope (%) 4.7 N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type**

N/A

Yes

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Curb Slope (%)